

# INDIANA REPEATER COUNCIL

## New Coordination

### Holder of Coordination

Name: Nicholas Klinger  
Call: KC9JOY  
Address: 451 Manor Drive  
City: Seymour, IN  
Zip: 47274

### Trustee Information

Name: Nicholas Klinger  
Call: KC9JOY  
Address: 451 Manor Drive  
City: Seymour, IN  
Zip: 47274  
E-mail: kc9joy@gmail.com  
Phone: 812-522-6570

### Date:

March 2, 2008

Repeater Call: KC9JOY  
Repeater City: Seymour, IN  
Region: South Central  
Band: 70 cm Band  
MHz In: 446.550 MHz  
MHz Out: 441.550 MHz  
RX Tone/Code: Carrier  
TX Tone/Code: None  
Location Address: 740 N. Chestnut  
Location City: Seymour, IN  
Tower Registration: none  
County: Jackson  
Latitude: 38 Deg 57' 56" N  
Longitude: 85 Deg 53' 32" W  
HAGL: 140 feet  
HAMSL: 740 feet  
Transmitter TPO: 40 w  
ERP: 100w  
Antenna pattern: Omni  
Isolation method: Duplexer  
ARRL: o

New System - March 2, 2008

### Confirmation of Coordinated Repeater

Your system as listed above is coordinated by The Indiana Repeater Council. **Any changes to your system such as HAAT or ERP, that will affect transmitter or user coverage must be re-coordinated.** If this is an update, technical data provided with the latest approved coordination or re-coordination will prevail for a valid coordination. System must be in full compliance with current FCC regulations and good Amateur operating practices. Unless otherwise specified, this system must be operated on a continuous basis. Failure to do so for a period of 60 days or more may subject this system to de-coordination. Waivers may be applied for in extenuating circumstances. Coordinations are granted on a basis of non-interference with existing systems coordinated by a coordinator recognized by the NFCC or the Indiana Repeater Council. We reserve the right to modify or discontinue this coordination as necessary if harmful interference occurs to one or more of these existing systems. CTCSS is recommended but not required and is left to the repeater owner or trustee's option unless otherwise specified.

**Updates must be filed with us every two years to assure coordination remains valid.**

IRC membership is not required for coordination. There is no charge for IRC services.

Indiana Repeater Council Coordinator /s/ Charles D. Sears Date: March 2, 2008

Charles D. Sears, N9MEW - IRC Coordinator

Geographical data verified by satellite imagery